

2. WORK PERFORMED

This section provides the official name, the most common alias, and the ID number for each well. Pertinent information regarding each well is also included (e.g., the date and type of maintenance that was done and the observations that were recorded).

2.1 ANP-08

WELL ID: 76

1. Project Name: Site-wide Maintenance for FY 2003
 2. Well Location: Test Area North (TAN)
 3. Date Maintenance Performed: Started: 1/28/03 Completed: 2/3/03
 4. Video Log Information: Video logging was not performed on this well.
 5. Maintenance Performed: Well maintenance consisted of pulling the pipe, pump, and electric cable from the well. The total depth of the borehole is 309.2 ft below land surface (bls). The well consisted of 260 ft of 4-in., galvanized pipe and the pump assembly. The electricity to the well house was disconnected, and the electrical assembly was dismantled. A boom truck was used to detach the building's removable roof and place it to the side. After removing a total of thirteen 20-ft rods, a 6-in. blind flange was installed at the wellhead, the roof was restored to its original position, and the pipes were left on pipe racks, as the scope outlined.
 6. Observations Recorded: The well house lock and concrete pad are in good condition. The electricity was disconnected from the building.
 7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT
- Field Lead: B. Reynolds/W. Jolley
- Crew: G. Jensen, J. Hansen, and T. Brower

2.2 TAN-21

WELL ID: 793

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: TAN
3. Date Maintenance Performed: Started: 1/27/03 Completed: 2/4/03
4. Video Log Information: The video log showed the water level at 215 ft bls. Visibility was lost at approximately 283 ft and not regained. Small pieces of bentonite were identified just before visibility was lost. As the camera was removed from the hole, significant amounts of bentonite were stuck to it.
5. Maintenance Performed: Well maintenance consisted of removing the pipe and pump assembly from the well, cleaning the well, and reinstalling the original pump. Recent sampling indicated significant amounts of bentonite in purge water. The original 2-horse power (hp) pump was removed, and a sand pump was run down to remove sediment and debris. A 5-hp pump was subsequently installed to a depth of 441.7 ft, and the well was purged for 23 minutes, producing approximately 200 gal of water. After approximately 23 minutes, the filter became plugged and pumping ceased. This pump assembly was removed, and the sediment in the hole was allowed to settle for 6 days so that the United States Geological Survey (USGS) could video the down-hole conditions. Because of the high turbidity and low visibility encountered during the video log, the cause of the sediment and bentonite in the well could not be determined. Upon consultation with project personnel, the original sampling pump was reinstalled to its original depth of 443.9 ft bls with 21 sections of 21-ft, stainless-steel discharge pipe. A water level access line consisting of 11 sections of 21-ft and one section of 22-ft, perforated, stainless-steel pipe was also installed.
6. Observations Recorded: The concrete pad, well cap, and lock were in satisfactory condition. The guard posts need to be repainted.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/ W. Jolley

Crew: G. Jensen, J. Hanson, and T. Brower

WELL ID 793

WELL NAME TAN 21

PROJECT NAME FY 03 TAN WELL MAINTENANCE

Reason for modification: Clean and redevelop the well.

Well Modification Log

START DATE 1/27/03 END DATE 2/4/03

INSTALLATION TEAM Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ NA ☐ no

Are measurements from top of casing or land surface? Casing

Use diagram explain modification

Pump Modification

Type	<u>Not Modified</u>
Manufacturer	
Model #	
Pump length	<u>2ft - 2in</u>
Top of pump	<u>441.7 ft bls</u>
Bottom of pump	<u>443.9 ft bls</u>
Inlet depth	<u>442.7 ft bls</u>
Horse power	<u>2 hp</u>
Flow rate	<u>Not measured</u>
Head	<u>Not measured</u>
Volts, Amps, Kw	
Phase	
Material	<u>Not Modified</u>
Motor leads/Plugs	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	<u>Not Modified</u>

Discharge Line (Riser Pipe) Modification

Material	<u>Stainless</u>
Diameter	<u>1 in.</u>
Height above ground (stick-up)	<u>1.5 ft.</u>
Depth BLS	<u>441.7 ft</u>

Water Level/Access Line Modification

Material	<u>Stainless</u>
Diameter	<u>1.5 in.</u>
Height above ground (stick-up)	<u>1.5 ft.</u>
Depth BLS	<u>251.5 ft</u>

Measure Point

Height above ground (stick-up)	<u>Not Modified</u>
--------------------------------	---------------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	<u>Not Modified</u>
Depth BLS	

Well Description

Casing condition	<u>X</u>	
Concrete pad	<u>X</u>	
Guard post		<u>X</u>
Screen	<u>X</u>	
Lock & cap	<u>X</u>	

Well/Description

Satisfactory	Needs repair
--------------	--------------

Comments:

Installed pump and discharge tubing, safety cable. No other modifications were made.

Video Logs: yes ☒ no ☐ date 2/2/03

Well jetted /cleaned: yes ☒ no ☐ date 1/27/03

Performed by: Dynatec

Signature and date: B. Reynolds 2/4/03

Figure 2-2. Well modification log for TAN-21.

2.3 TANT-MON-A-013 (TAN-39)

WELL ID: 1165

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: TAN
3. Date Maintenance Performed: Started: 2/10/03 Completed: 2/10/03
4. Video Log Information: Video logging was not performed on this well.
5. Maintenance Performed: Maintenance at TAN-39 consisted of two parts. First, the carbon-steel discharge line was replaced with stainless-steel pipe after the well house was removed. During installation of the new discharge line, the dielectric coupler was relocated to the top of the string, just below the landing plate. Second, the transducer was replaced. When the pump and pipe were removed from the well, Waste Generator Services (WGS) collected residue from the pump area for analysis. WGS provided the sample analysis results directly to the 1-07B project. The pump and pipe were then returned to their original depths, and the well house was reinstalled.
6. Observations Recorded: The surface completion concrete, well house, and electrical assemblies were in very good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/W. Jolley

Crew: G. Jensen, J. Hanson, and T. Brower

WELL ID 1165

WELL NAME TANT-MON-A-013 (TAN-39)

PROJECT NAME FY-03 TAN WELL MAINTENANCE

Reason for modification: Replace well pipe and transducer due to corrosion of the carbon steel pipe.

1165

TANT-MON-A-013 (TAN-39)

FY-03 TAN WELL MAINTENANCE

Replace well pipe and transducer due to corrosion of the carbon steel pipe.

Well Modification Log

START DATE 2/10/03

END DATE 2/10/03

Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ yes ☒ no

Are measurements from top of casing or land surface? Land Surface

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Material	Stainless
Diameter	3 in
Height above ground (stick-up)	Not modified
Depth BLS	250 ft

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Comments:

WGS attended the site to collect residue samples from the pump area to be tested.

Relocated dielectric coupler to top of discharge line, just below the landing plate.

Video Logs: yes no X date

Well jetted /cleaned: yes no X date

Performed by: Dynatec

Signature and date: B. Reynolds 2/12/03

Figure 2-3. Well modification log for TANT-MON-A-013.

2-6

2.4 TANT-MON-A-014 (TAN-40)

WELL ID: 1166

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: TAN
3. Date Maintenance Performed: Started: 2/11/03 Completed: 2/25/03
4. Video Log Information: Video logging was not performed on this well.
5. Maintenance Performed: Well maintenance consisted of two parts. First, the carbon-steel discharge line was replaced with stainless-steel pipe after the well house was removed. During installation of the stainless-steel discharge line, the dielectric coupler was relocated to the top of the string, just below the landing plate. Second, the transducer was replaced. While the pump and pipe were removed from the well, WGS collected residue from the elbow located above the landing-plate and pump area for analysis. The pump and pipe were then returned to their original depths, and the well house was reinstalled.
6. Observations Recorded: The surface completion concrete, well house, and electrical assemblies were in very good condition. Carbon-steel casing pulled from the hole had minor corrosion and rust. The pump appeared to be in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, Utah

Field Lead: B. Reynolds/W. Jolley

Crew: G. Jensen, J. Hansen, and T. Brower

WELL ID 1166

WELL NAME TANT-MON-A-014 (TAN-40)

PROJECT NAME FY 2003 TAN Well Maintenance

Reason for modification: Replacement of riser pipe.

Well Modification Log

START DATE 2/11/03

INSTALLATION TEAM Dynatec

END DATE 2/25/03

Is this a pump replacement?

☒

yes

☐

no

If yes was pump returned to original depth?

NA

yes

☐

no

Are measurements from top of casing or land surface?

Land Surface

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Well Description

Casing condition	X	Satisfactory	Needs repair
Concrete pad	X		
Guard post	X		
Screen	X		
Lock & cap	X		

Discharge Line (Riser Pipe) Modification

Material	Stainless steel
Diameter	3 inch
Height above ground (stick-up)	3 ft
Depth BLS	233.5 ft

Water Level/Access Line Modification

Material	Not Applicable
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Use diagram explain modification

Pump Modification

Type	Not Modified	
Manufacturer		
Model #		
Pump length		
Top of pump		233.5 ft
Bottom of pump		236 ft
Inlet depth		235 ft
Horse power		
Flow rate	Not Modified	
Head		
Volts, Amps, Kw		
Phase		
Material		
Motor leads/Plugs		

Protective Casing

Material	Not Modified
Diameter	
Height above ground (stick-up)	

Comments:

Replaced carbon steel downcomer pipe with stainless steel and replaced the transducer.

Relocated dielectric coupler (beneath landing plate)

Video Logs: yes no X date

Well jetted /cleaned: yes no X date

Performed by: Dynatec

Signature and date: B. Reynolds 2/25/03

Figure 2-4. Well modification log for TANT-MON-A-014.

2.5 TANT-INJ-A-053A (TAN-53A)

WELL ID: 1339

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: TAN
3. Date Maintenance Performed: Started: 1/30/03 Completed: 1/30/03
4. Video Log Information: No video log was performed on this well.
5. Maintenance Performed: Maintenance at this well consisted of pulling 10 sections of 4-in., carbon-steel downcomer pipe. The bottom three sections of pipe were removed. A dielectric flange was installed at 146 ft bls. Four sections of 4-in., stainless-steel downcomer pipe were installed as the bottom section of the string below the flange. Seven of the original carbon-steel pipes were used to complete the string to previous stick-up. The final depth of the string is 231 ft bls.
6. Observations Recorded: The concrete pad, wellhead box, and lock were in satisfactory condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/W. Jolley

Crew: G. Jensen, J. Hanson, and T. Brower

WELL ID 1339

Dynatec


INSTALLATION TEAM

PROJECT NAME	FY 03 TAN WELL MAINTENANCE

Reason for modification: Replaced 3 carbon steel 4in. Down pipe with stainless steel pipe of the same

yes
no

Are measurements from top of casing or land surface? Land Surface



Use diagram explain modification

[illegible]

<i>Well Description</i>	Satisfactory	Needs repair

Discharge Line (Riser Pipe) Modification

Material
Stainless/Carbon Steel

Water Level Access Line Modification

Not Applicable

Measure Point

Height above ground	1.5 + Modified
---------------------	----------------

Well Casing

Not Modified

Pipe was pulled.

B. Reynolds 2/3/03

Figure 2-5. Well modification log for TANT-INJ-A-053A.

2.6 ARA-MON-A-001

WELL ID: 1003

1. Project Name: Site-wide Well Maintenance for FY 2003
 2. Well Location: Auxiliary Reactor Area (ARA)
 3. Date Maintenance Performed: Started: 6/4/03 Completed: 6/17/03
 4. Video Log Information: Video logging was performed on 6/10/03.
 5. Geophysical Log Information: Gyro-deviation logging was performed on 6/12/03.
 6. Maintenance Performed: Maintenance at this well included replacing the original pump; replacing the galvanized discharge (1.25-in.) and access (1-in.) pipe with Schedule-40, stainless-steel pipe; and equipping the pump/motor assembly with 8-gauge, heavy-duty electrical wire and a 3-phase, 30A/600V plug (NEMA #L17-30). Upon completion of maintenance activities, the subcontractor energized the pump to ensure it worked properly and installed a lockable well cap.
 7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
 8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT
- Field Lead: B. Reynolds/L. Lopez
- Crew: Joe Lambert and Danny Waddoups

WELL ID 1003

WELL NAME ARA-MON-A-001

PROJECT NAME FY 03 Site Wide Well Maintenance

Reason for modification: Needed stainless discharge and access pipe to minimize corrosion. Also replaced the wellhead box with a lockable well cap

Well Modification Log

START DATE 6/4/03

END DATE 6/17/03

Dynatec

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☒ yes ☐ no

Are measurements from top of casing or land surface? Land Surface

Elevation of brass cap? Not changed

Stick up of well casing? Not changed

Use diagram explain modification

Pump Modification

Type	4 in. Submersible
Manufacturer	Grundfos/Franklin Electric
Model #	10S 30-34
Pump length	4.58 ft
Top of pump	620.5 ft
Bottom of pump	625.1 ft
Inlet depth	624.1 ft
Horse power	3 hp
Flow rate	Approximately 10 gpm
Head	593 ft
Volts, Amps, Kw	230V, 2.2 KW, 9.5 A
Phase	3 phase
Material	Stainless Steel
Motor leads/Plugs	8 gauge/ 30A 600V

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Discharge Line (Riser Pipe) Modification

Material	Stainless Steel
Diameter	1.25 in
Height above ground (stick-up)	2.5 ft
Depth BLS	620.5ft

Water Level Access Line Modification

Material	Stainless
Diameter	1 in.
Height above ground (stick-up)	2.5
Depth BLS	590.5

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Comments:

An aluminum well cap with lock was installed.

Video Logs: yes ☐ no ☐ date 6/10/03

Well jetted /cleaned: yes ☒ no ☐ date 6/10/03

Performed by: Dynatec

Signature and date: Roe Reynolds 11/11/03

Figure 2-6. Well modification log for ARA-MON-A-001.

2.7 PBF-MON-A-003

WELL ID: 1087

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: Power Burst Facility (PBF)
3. Date Maintenance Performed: Started: 6/4/03 Completed: 6/23/03
4. Video Log Information: Video logging was not performed on this well.
5. Maintenance Performed: Maintenance at this well consisted of two parts. On 6/4/03, the stick-up of the surface casing was reduced 2 ft to lessen the difficulty of access. The wire was also reduced accordingly. An aluminum lockable well cap was installed to complete the first part of maintenance at this well. The second part consisted of replacing the pump, pipe, and wire. A new pump was installed, galvanized discharge and access pipe was replaced with stainless-steel pipe, and new wire equipped with a 30A/600V plug (NEMA #L17-30) was installed. The discharge line is 1.25-in., Schedule-40, stainless steel pipe, and the access line is 1-in., Schedule-40, stainless-steel pipe. The well was jetted and cleaned on 6/23/03 before reinstallation of the pump, pipe, and wire.
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/W. Jolley

Crew: J. Lambert, D. Waddoups, and I. Perkes

WELL ID 1087

WELL NAME PBF-MON-A-003

PROJECT NAME FY 03 Sitewide Well Maintenance

Reason for modification: Shorten surface casing, install well cap and replace pump, pipes, and electrical cable.

Well Modification Log

START DATE 6/4/03

END DATE 6/23/03

Dynatec

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☒ yes ☐ no

Are measurements from top of casing or land surface? ☐ Land Surface

Elevation of brass cap? ☐ Not changed ☒ Not changed

Stick up of well casing? ☐ Needs repair ☒ Satisfactory

Use diagram explain modification

Pump Modification

Type	Submersible
Manufacturer	Grundfos/Franklin Electric
Model #	10S 30-34
Pump length	4.58 ft
Top of pump	563.5 ft
Bottom of pump	568.1 ft
Inlet depth	567.1 ft
Horse power	3 hp
Flow rate	12 gmp
Head	520.5 ft
Volts, Amps, Kw	230V, 2.2KW, 9.5A
Phase	3 phase
Material	Stainless steel
Motor leads/Plugs	8 gauge (30A, 600V)

Discharge Line (Riser Pipe) Modification

Material	Stainless Steel
Diameter	1.25 in.
Height above ground (stick-up)	2 ft 8 in.
Depth BLS	563.5 ft

Water Level Access Line Modification

Material	Stainless Steel
Diameter	1 in.
Height above ground (stick-up)	2 ft 8 in.
Depth BLS	546

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	Carbon Steel
Diameter	12 in.
Height above ground (stick-up)	3 ft

Protective Casing

Material	Carbon Steel
Diameter	12 in.
Height above ground (stick-up)	3 ft

Comments: Changed the wire, pump, pipe, and electrical plug. The pump was tested and proven to be in working condition.

Video Logs: yes ☐ no ☒ date 6/23/03

Well jetted /cleaned: yes ☒ no ☐ date 6/23/03

Performed by: Dynatec

Signature and date: Roe Reynolds 8/5/03

Figure 2-7. Well modification log for PBF-MON-A-003.

2.8 PBF-MON-A-004

WELL ID: 1094

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: PBF
3. Date Maintenance Performed: Started: 6/4/03 Completed: 6/17/03
4. Video Log Information: Video logging was performed on 6/12/03.
5. Deviation Log: The USGS performed gyro-deviation logging on 6/12/03.
6. Maintenance Performed: Maintenance at this well included replacing the previous pump; replacing the previous galvanized discharge (1.25-in.) and access (1-in.) pipe with stainless-steel, Schedule-40 pipe; and equipping the pump/motor assembly with 8-gauge, heavy-duty electrical wire and a 3-phase, 30A/600V (NEMA #L17-30) plug. Upon completion of the pump, the subcontractor energized the pump to ensure it functioned properly and installed a lockable well cap.
7. Observations Recorded: The surface completion pad needs to be repaired, but the impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/L. Lopez

Crew: J. Lambert, D. Waddoups, G. Jensen, and L. Rosario

WELL ID 1094 **Well Modification Log** START DATE 6/4/03 END DATE 6/17/03

WELL NAME PBF-MON-A-004 (PBF-MON-4) Dynatec

PROJECT NAME FY 03 Sitewide Well Maintenance INSTALLATION TEAM

Reason for modification: Replaced the pump, pipe and electrical assembly; jetted and cleaned the borehole; and replaced the well head box with and lockable well cap.

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☒ yes ☐ no If yes was pump returned to original depth? ☒ yes ☐ no

Are measurements from top of casing or land surface? Land Surface



Pump Modification

Type	Submersible
Manufacturer	Grundfos/Franklin Electric
Model #	10S 30-34
Pump length	4.58 ft
Top of pump	526.3 ft
Bottom of pump	530.9 ft
Inlet depth	529.9 ft
Horse power	3 hp
Flow rate	10-12 gpm
Head	497 ft
Volts, Amps, Kw	230V/2.2Kw/9.5A
Phase	3 ph
Material	Stainless Steel
Motor leads/Plugs	8 gauge (30A/600V plug)

Protective Casing

Material	Not Modified
Diameter	Not Modified
Height above ground (stick-up)	Not Modified

Well Description	Satisfactory	Needs repair
Casing condition	X	
Concrete pad		X
Guard post	X	
Screen	X	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification

Material	Stainless Steel
Diameter	1.25 in
Height above ground (stick-up)	2.6 ft
Depth BLS	526.3 ft

Water Level Access Line Modification

Material	Stainless Steel
Diameter	1 in.
Height above ground (stick-up)	2.6 ft
Depth BLS	477.4 ft

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	Not Modified
Diameter	Not Modified
Height above ground (stick-up)	Not Modified
Depth BLS	Not Modified

Comments: _____

Video Logs: yes ☒ no ☐ date 6/12/03 Signature and date: Boe Reynolds 8/5/03

Well jetted /cleaned: yes ☒ no ☐ date 6/11/03

Performed by: Dynatec

Figure 2-8. Well modification log for PBF-MON-A-004.

2.9 ICPP-MON-A-230 (TANK FARM 230)

WELL ID: 1442

1. Project Name: Idaho Nuclear Technology and Engineering Center (INTEC) Well Maintenance for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/6/03 Completed: 5/12/03
4. Video Log Information: Video logging was not performed on this well.
5. Maintenance Performed: Maintenance at this well consisted of installing a pump and pipe, including the electrical cable. Work began on 5/6/03 by lowering a 3-hp pump attached to 1.25-in., stainless-steel discharge line. A 1-in., water-access line was installed to 464 ft 11 in. bls. The pump was installed at 473.92 ft bls on 5/7/03 and was wired with 8-gauge, heavy-duty electrical wire and a 30A/600V (NEMA #L17-30) plug. The pump was tested for operational readiness on 5/12/03.
6. Observations Recorded: The surface completion concrete is cracked and sectioned into three portions. Impingement posts are in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/W. Jolley

Crew: S. Tawater, M. Becker, and I. Perkes

WELL ID 1442

WELL NAME ICPP-MON-A-230 (Tank Farm 230)

PROJECT NAME FY 03 Well Maintenance at INTEC

Well Modification Log

START DATE 5/6/03

INSTALLATION TEAM Dynatec

END DATE 5/12/03

Elevation of brass cap? Not Changed

Reason for modification: Installed a pump, piping and electrical cable with plug to enable monitoring of the SRPA. No pump assembly existed previous to this installation.

Is this a pump replacement?

☒ yes
☐ no

If yes was pump returned to original depth?

☐ NA
☐ yes
☐ no

Are measurements from top of casing or land surface?

☐ Land Surface

Stick up of well casing? Not Changed

Needs repair

Casing condition	X	
Concrete pad		X
Guard post	X	
Screen	NA	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification

Material	Stainless Steel
Diameter	1.25 in.
Height above ground (stick-up)	2.4 ft
Depth BLS	473.92 ft

Water Level/Access Line Modification

Material	Stainless Steel
Diameter	1 in.
Height above ground (stick-up)	2.4 ft
Depth BLS	464 ft 11 in.

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Pump Modification

Type	Submersible
Manufacturer	Grundfos
Model #	10S 30-34
Pump length	4.58 ft
Top of pump	473.92 ft
Bottom of pump	478.5 ft
Inlet depth	478 ft
Horse power	3 hp
Flow rate	Not Measured
Head	Not Measured
Volts, Amps, Kw	230V/9.5A/2.2KW
Phase	3 phase
Material	Stainless Steel
Motor leads/Plugs	8 gauge (30A/600V plug)

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Use diagram explain modification

Comments:

Video Logs: yes no X date

Well jetted /cleaned: yes no X date

Performed by: Dynatec

Signature and date: Boe Reynolds 9/5/03

Figure 2-9. Well modification log for ICPP-MON-A-230.

2.10 FIRE STATION WELL

WELL ID: 158

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: Central Facilities Area (CFA)
3. Date Maintenance Performed: Started: 12/20/02 Completed: 1/9/03
4. Video Log Information: The USGS performed video logging on 12/20/02.
5. Maintenance Performed: Maintenance at this well included video and deviation logging and removing the pump, discharge pipe, and electrical assembly. A new 15-hp, Grundfos, submersible pump was installed with a 2-in. discharge line and a 30A/600V plug (NEMA #L17-30) motor lead. This pump was installed to obtain water suitable for injection during drilling and coring.
6. Observations Recorded: Surface completion pads were in good condition; however, no impingement posts are present.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: K. Dooley

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 158

WELL NAME Fire Station Well

PROJECT NAME Non-Routine Well Modification

Reason for modification: Installed pump to enable a source of water suitable for coring and drilling projects.

Well Modification Log

START DATE 12/20/02 END DATE 1/9/03

INSTALLATION TEAM Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☐ NA ☐ yes ☐ no

Are measurements from top of casing or land surface? Land Surface

Use diagram explain modification

Pump Modification

Type	Submersible
Manufacturer	Goulds
Model #	70J15
Pump length	4.4 ft
Top of pump	487.6 ft
Bottom of pump	492 ft
Inlet depth	491 ft
Horse power	15 hp
Flow rate	130 gpm
Head	434 ft
Volts, Amps, Kw	460V/20.8A/20
Phase	3 phase
Material	Stainless Steel
Motor leads/Plugs	600V, 30A

Discharge Line (Riser Pipe) Modification

Material	Carbon Steel
Diameter	2 in.
Height above ground (stick-up)	37 in.
Depth BLS	487.6 ft

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	Not Applicable
Depth BLS	

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Comments:

Unable to jet water.

Video Logs: yes ☐ no ☐ date 12/20/02

Well jetted /cleaned: yes ☐ no ☐ date 1/7/03

Performed by: Dynatec

Signature and date:

Kirk Dooley 1/9/03

Figure 2-10. Well modification log for Fire Station Well.

2-20

2.11 ICPP-1782

WELL ID: 1782

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/6/03 Completed: 6/4/03
4. Video Log Information: Video logging was not performed on this well.
5. Deviation Log Information: The USGS performed deviation logging on 5/6/03.
6. Maintenance Performed: Maintenance at this well included removal of the pump, discharge/access pipe, and electrical assembly. The well was jetted with 7.5 gal of Aquaclear MGA to remedy bacterial buildup on the pump and pipe. Once the pH levels were neutral, all well equipment (i.e., pump, pipe, and wire) was reinstalled to their original depths (508 ft).
7. In June, project personnel were directed to raise the pump 32 ft. The pump was raised by removing two sections of 21-ft discharge line and then adding a single 10-ft section.
8. Observations Recorded: Surface completion pads and impingement posts were in good condition.
9. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 1782 **Well Modification Log**
WELL NAME ICPP-1782 START DATE 5/6/03 END DATE 6/4/03
PROJECT NAME ICDF Borehole Deviation Logging INSTALLATION TEAM Dynatec
Reason for modification: Bacteria build up on the pump and pipe.

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Well Description	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	
	476 ft

Water Level Access Line Modification

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	
	466 ft

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	-------------------------

Well Casing

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Is this a pump replacement? ☐ yes ☒ no If yes was pump returned to original depth? ☐ NA ☐ yes ☐ no

Are measurements from top of casing or land surface? Land Surface

Use diagram explain modification

<i>Pump Modification</i>	
Type	Not Modified
Manufacturer	
Model #	
Pump length	3.5 ft
Top of pump	476 ft
Bottom of pump	479.5 ft
Inlet depth	478 ft
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing

Material	Not Modified
Diameter	
Height above ground (stick-up)	

Comments: The pump was pulled on 5/6/03 and 7.5 gallons of Aquadear MGA was added on 5/28/03 to treat bacteria. Aquadear MGA was added through a jetting tool as the well was cleaned. After completion of maintenance the pumps were raised 32 ft by removing two 21 ft sections of discharge line and adding one 10 ft section.

Video Logs: yes no X date Signature and date: Boe Reynolds 6/4/03

Well jetted /cleaned: yes X no date 6/3/03

Performed by: Dynatec

Figure 2-11. Well modification log for ICPP-1782.

2.12 ICPP-1783

WELL ID: 1783

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/6/03 Completed: 6/4/03
4. Video Log Information: Video logging was not performed on this well.
5. Deviation Log Information: The USGS performed deviation logging on 5/6/03.
6. Maintenance Performed: Maintenance at ICPP-1783 included removal of the pump, discharge/access pipe, and electrical assembly. Once the pump was removed, observations indicated a buildup of bacteria on the pump and pipe. The well was jetted with 7.5 gal of Aquaclear MGA to remedy bacterial buildup on the pump and pipe. Once the pH levels were neutral, all well equipment (i.e., pump, pipe, and wire) was reinstalled to its original depth (510.8 ft).
7. In June, project personnel were directed to raise the pump 32 ft. The pump was raised by removing two sections of 21-ft discharge line and then adding a single 10-ft section.
8. Observations Recorded: Surface completion pads and impingement posts were in good condition.
9. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WFII ID 1783

WELL NAME	START DATE	END DATE
JCPP-1783	5/6/03	6/4/03

PROJECT NAME: ICDP Borehole Deviation Logging INSTALLATION TEAM: Dynatec

Reason for modification:	Bacteria was observed during borehole deviations.	Elevation of brass can?	Not Changed


Elevation of brass cap? Not Changed

Stick 'em up of well casing?

is this a pump replacement? ☐ yes ☐ no

If yes was pump returned to original depth? ☐ X no ☐ NA yes

Are measurements from top of casing or land surface? Land Surface



Use diagram explain modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	478.8 ft
Bottom of pump	482.3 ft
Inlet depth	481.3 ft
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing	
Material	No Modifications
Diameter	
Height above ground (stick-up)	

<i>Well Description</i>	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification

Material	No Modification
Diameter	
Height above ground (stick-up)	
Depth BLS	
	478.8 ft

Water Level Access Line Modification

Material	No Modification
Diameter	
Height above ground (stick-up)	
Depth BLS	
	468.8 ft

Measure Point

Height above ground (stick-up)	
-----------------------------------	--

Well Casing

Material	No Modifications
Diameter	
Height above ground (stick-up)	
Depth BLS	

Comments:
Approximately 7.5 gallons of Aquaclear MGA was used to treat bacterial build up on 5/29/03, which was injected through the jetting tool. After completion of maintenance direction came to raise the pump. The pump was raised 32 ft by removing two 21 ft sections of the pump column and adding a 10 ft section.

Video Logs: yes no X date 6/4/04

Well letted /cleaned:	yes	no	date
	X		5/29/03

Performed by: Dynatec

Figure 2-12. Well modification log for ICPP-1783.

2.13 ICPP-1800

WELL ID: 1800

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/6/03 Completed: 6/4/03
4. Video Log Information: Video logging was performed on 5/6/03.
5. Deviation Log Information: The USGS performed deviation logging on 5/6/03.
6. Maintenance Performed: Maintenance at this well included removal of the pump, discharge/access pipe, and electrical assembly. Once the pump was removed, observations indicated a buildup of bacteria on the pump and pipe. The well was jetted with 7.5 gal of Aquaclear MGA to remedy bacterial buildup on the pump and pipe. Once the pH levels were neutral, all well equipment (i.e., pump, pipe, and wire) was reinstalled to its original depth (508.1 ft).
7. In June, project personnel were directed to raise the pump 32 ft. The pump was raised by removing two sections of 21-ft discharge line and then adding a single 10-ft section.
8. Observations Recorded: Surface completion pads and impingement posts were in good condition.
9. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 1800 *Well Modification Log*

WELL NAME ICPP-1800 START DATE 5/6/03 END DATE 6/4/03


PROJECT NAME ICDF Borehole Deviation Logging INSTALLATION TEAM Dynatec

Reason for modification: Bacteria was observed on the pump and pipe during deviation logging. Elevation of brass can? Not Changed

Reason for modification:	Elevation of brass cap?	Stick up of well casing?
Bacteria was observed on the pump and pipe during deviation logging.	Not Changed	Not Changed

Is this a pump replacement? ☐ yes ☒ no

Are measurements from top of casing or land surface? Land Surface



Use diagram explain modification

<i>Pump Modification</i>	
Type	
Manufacturer	
Model #	
Pump length	
Top of pump	476.1 ft
Bottom of pump	479.6 ft
Inlet depth	478.6 ft
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/plugs	

<i>Protective Casing</i>	
Material	Not Modified
Diameter	
Height above ground (stick-up)	

<i>Well Description</i>	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification

Material	Not Notified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	466.1 ft

Measure Point

Height above ground (stick-up)	Not Modified
-----------------------------------	--------------

Well Casing

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Comments: The pump was pulled on 5/6/03 and treated using 10 gallons of Aquaclear MGA on 5/29/03. Cleaning was performed through swabbing and jetting the borehole. After completion of maintenance direction came to raise the pump 32 ft. The pump was raised by removing two 21 ft sections of the pump column and then adding a 10 ft section.

Video Logs:	yes	no	date
	X		5/6/03

Well	Jetted /cleaned:	yes	X	no	date
					5/29/03

Performed by: Dynatec

Figure 2-13. Well modification log for ICPP-1800.

2.14 ICPP-1829

WELL ID: 1829

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/6/03 Completed: 6/4/03
4. Video Log Information: Video logging was not performed on this well.
5. Deviation Log Information: The USGS performed deviation logging on 5/6/03.
6. Maintenance Performed: Maintenance at ICPP-1829 included removal of the pump, discharge/access pipe, and electrical assembly. Once the pump was removed, observations indicated a buildup of bacteria on the pump and pipe. The well was jetted with 7.5 gal of Aquaclear MGA to remedy bacterial buildup on the pump and pipe. Once the pH levels were neutral, all well equipment (i.e., pump, pipe, and wire) was reinstalled to its original depth (508.3 ft).

In June, project personnel were directed to raise the pump 32 ft. The pump was raised by removing two sections of 21-ft discharge line and then adding a single 10-ft section.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 1829 **Well Modification Log** START DATE 5/6/03 END DATE 6/4/03
WELL NAME ICPP-1829 PROJECT NAME ICDF Borehole Deviation Logging INSTALLATION TEAM Dynatec
Reason for modification: Bacterial build up was observed on the pump and pipe during deviation logging.


Elevation of brass cap? Not Changed
Stick up of well casing? Not Changed

Well Description	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

Is this a pump replacement? ☐ yes ☒ no
If yes was pump returned to original depth? ☐ yes ☒ no

Are measurements from top of casing or land surface? Land Surface

Use diagram explain modification



Pump Modification

Type	
Manufacturer	No Modifications
Model #	
Pump length	
Top of pump	476.3 ft
Bottom of pump	479.8 ft
Inlet depth	478.8 ft
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	No Modification
Material	
Motor leads/Plugs	

Protective Casing

Material	No Modifications
Diameter	
Height above ground (stick-up)	

Discharge Line (Riser Pipe) Modification

Material	No Modifications
Diameter	
Height above ground (stick-up)	
Depth BLS	476.3 ft

Water Level Access Line Modification

Material	No Modifications
Diameter	
Height above ground (stick-up)	
Depth BLS	466.3 ft

Measure Point

Height above ground (stick-up)	

Well Casing

Material	No Modifications
Diameter	
Height above ground (stick-up)	
Depth BLS	

Comments: Used 7.5 gallons of Aqualbear MGA to treat bacteria in the well on 5/28/03. After completion of maintenance direction came to raise the pump 32 ft. The pump was raised by removing two 21 ft section of pump column and then adding a 10 ft section.

Video Logs: yes ☐ no ☒ date 6/3/03 Signature and date: Boe Reynolds 6/04/03
Well jetted /cleaned: yes ☒ no ☐ date 6/3/03
Performed by: Dynatec

Figure 2-14. Well modification log for ICPP-1829.

2.15 ICPP-1831

WELL ID: 1831

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/5/03 Completed: 6/4/03
4. Video Log Information: Video logging was performed on 5/6/03.
5. Deviation Log Information: The USGS performed deviation logging on 5/6/03.
6. Maintenance Performed: Maintenance at ICPP-1831 included removal of the pump, discharge/access pipe, and electrical assembly. Once the pump was removed, observations indicated a buildup of bacteria on the pump and pipe. The well was jetted with 7.5 gal of Aquaclear MGA to remedy bacterial buildup on the pump and pipe. Once the pH levels were neutral, all well equipment (i.e., pump, pipe, and wire) was reinstalled to its original depth (508 ft).
7. In June, project personnel were directed to raise the pump 32 ft. The pump was raised by removing two sections of 21-ft discharge line and then adding a single 10-ft section.
8. Observations Recorded: Surface completion pads and impingement posts were in good condition.
9. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 1831

WELL NAME	ICPP-1831	START DATE	5/5/03	END DATE	6/4/03
-----------	-----------	------------	--------	----------	--------


WELL NAME	ICDF Borehole Deviation Logging	START DATE	END DATE
PROJECT NAME	ICDF Borehole Deviation Logging	INSTALLATION TEAM	Dynatec

Reason for modification: Bacteria was observed during deviation logging.

Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ NA yes ☒ no

Are measurements from top of casing or land surface? Land Surface



Use diagram explain modification

Pump Modification	
Type	Not Modified
Manufacturer	
Model #	
Pump length	
Top of pump	476 ft
Bottom of pump	479.5 ft
Inlet depth	478.5 ft
Horse power	Not Modified
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing	
Material	
Diameter	
Height above ground (stick-up)	

Comments:

The well was cleaned with 7.5 gallons of Aquaclear MGA added to the well via the jetting tool. After completion of maintenance to raise the pump 32 ft. The pump was raised by removing two 21 ft sections of the pump column and then adding a 10 ft section.

Video Logs:	yes	X	no	date	5/6/03
-------------	-----	---	----	------	--------

Well jetted /cleaned: yes X no date 5/28/03

Performed by: Dynatec

Figure 2-15. Well modification log for ICPP-1831.

2.16 CPP-33-4-1 (CPP-33-4)

WELL ID: 764

1. Project Name: INTEC Well Maintenance for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/7/03 Completed: 5/8/03
4. Video Log Information: The video located the water at 97 ft bls, the bailer at 117 ft bls, and the bottom of the hole at approximately 118.2 ft bls. The casing appeared to be in fair condition.
5. Maintenance Performed: Maintenance at CPP-33-4-1 consisted of attempts to remove a down-hole obstruction. Several attempts failed to remove the obstruction, which was determined to be a bailer lost during sampling activities. A video taken of the hole indicated the bailer had been forced by fishing tools to the bottom of the well. Project personnel determined that sampling activities could resume with minimal interference. The bailer remains in the bottom of the well.
6. Observations Recorded: Surface completion pads and impingement posts were in excellent condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/W. Jolley

Crew: S. Tawater, M. Becker, and I. Perkes

Well Modification Log

WELL NAME

CPP-33-4-1 (CPP-33-4)

START DATE

5/7/03

END DATE

5/8/03

PROJECT NAME

FY 03 Well Maintenance at INTEC

INSTALLATION TEAM

Dynatec

Reason for modification:

Remove down-hole obstruction

Elevation of brass cap?

Not Changed

Stick up of well casing?

Not Changed

Is this a pump replacement?

☐ yes
☒ no

If yes was pump returned to original depth?

☐ yes
☒ no

Are measurements from top of casing or land surface?

NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
Not Modified	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
Not Modified	

Comments:

Tried unsuccessfully to retrieve a stuck bailer and treble hook lost in attempt to fish the bailer.

Succeeded in moving the obstruction to the bottom of the borehole enabling sample collection.

Video Logs:

yes ☒ no ☐ date 5/8/03

Well jetted /cleaned:

yes ☐ no ☒ date

Performed by:

Dynatec

Signature and date:

Boe Reynolds 8/5/03

Figure 2-16. Well modification log for CPP-33-4-1.

2.17 ICPP-SCI-P-249 (CS-CH)

WELL ID: 1445

1. Project Name: INTEC Well Maintenance for FY 2003
 2. Well Location: INTEC
 3. Date Maintenance Performed: Started: 5/8/03 Completed: 5/8/03
 4. Video Log Information: The video located a 2-in.-long, 3/4-in.-diameter pipe used as a weight to help lower bailers lodged at approximately 80 ft bls.
 5. Maintenance Performed: Maintenance at ICPP-SCI-249 consisted of attempting to remove a down-hole obstruction. Several attempts were made to remove the obstruction from the hole, which was presumed to be a bailer lost during sampling activities. Three weights similar to the weight described above under video log information were retrieved from the well, but the bailer was lodged at the bottom of the well and was left there. However, project personnel determined that sampling activities could resume with minimal interference.
 6. Observations Recorded: Surface completion pads and impingement posts were in excellent condition.
 7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT
- Field Lead: B. Reynolds/W. Jolley
- Crew: S. Tawater, M. Becker, and I. Perkes

WELL ID 1445

Elevation of brass can? Not Changed

Stick up of well casing?


Not Changed

Stick up of well casing?

Not Changed

yes
no

Are measurements from top of casing or land surface? NA



Use diagram explain modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Material	
Diameter	
Height above ground (stick-in)	

<i>Well Description</i>	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

Material	Not Applicable
Diameter	
Height above ground (stick-up)	
Depth BLS	

Material	Not Applicable
Diameter	
Height above ground (stick-up)	
Depth BLS	

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Video Logs: yes ☒ no ☐ date 5/8/03

Well jetted /cleaned:	yes	no	X	date

Performed by: Dynatec

Figure 2-17. Well modification log for ICPP-SCI-P-249.

2.18 PW-2

WELL ID: 258

1. Project Name: INTEC Well Maintenance for FY 2003
 2. Well Location: INTEC
 3. Date Maintenance Performed: Started: 5/6/03 Completed: 5/6/03
 4. Video Log Information: Video logging was not performed on this well.
 5. Maintenance Performed: Maintenance at PW-2 consisted of replacing the existing concrete surface pad. On 5/6/03, the existing surface pad was removed using crowbars and hammers. A new pad was installed the same day.
 6. Observations Recorded: The brass cap should be resurveyed.
 7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT
- Field Lead: B. Reynolds/W. Jolley
- Crew: D. Waddoups and Joe Lambert

WELL ID 258

WELL NAME PW-2

PROJECT NAME FY 03 Well Maintenance at INTEC

Reason for modification: Deterioration of concrete pad.

START DATE 5/6/03

INSTALLATION TEAM Dynatec

END DATE 5/6/03

Well Modification Log

Elevation of brass cap? Resurvey

Stick up of well casing? Not Changed

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☐ yes ☒ no

Are measurements from top of casing or land surface? NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
--------------------------------	--

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Comments:

Removed previous pad and installed a new concrete pad. Brass cap should be resurveyed.

Video Logs: yes no X date

Well jetted /cleaned: yes no X date

Performed by: Dynatec

Signature and date: Roe Reynolds 11/11/03

Figure 2-18. Well modification log for PW-2.

2.19 PW-4

WELL ID: 260

1. Project Name: INTEC Well Maintenance for FY 2003
 2. Well Location: INTEC
 3. Date Maintenance Performed: Started: 5/6/03 Completed: 5/6/03
 4. Video Log Information: Video logging was not performed on this well.
 5. Maintenance Performed: Maintenance at PW-4 consisted of replacing the existing concrete surface pad. On 5/6/03, the existing surface pad was removed using crowbars and hammers. A new pad was installed the same day.
 6. Observations Recorded: The brass cap should be resurveyed.
 7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT
- Field Lead: B. Reynolds/W. Jolley
- Crew: D. Waddoups and Joe Lambert

Well Modification Log

WELL ID 260

WELL NAME PW-4

PROJECT NAME FY 03 Well Maintenance at INTEC

Reason for modification: Deterioration of concrete pad.

START DATE 5/6/03 END DATE 5/6/03

INSTALLATION TEAM Dynatec


Elevation of brass cap? Resurvey

Reason for modification: Deterioration of concrete pad.

Is this a pump replacement?

☒ X If yes was pump returned to original depth?

Are measurements from top of casing or land surface? NA



<i>Pump Modification</i>	
Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing	
Material	
Diameter	
Height above ground (stick-up)	Not Modified

<i>Well Description</i>	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	NA	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification	
Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification	
Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

<i>Measure Point</i>	
Height above ground (stick-up)	Not Modified

Well Casing	
Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Removed previous pad and installed a new concrete pad. Brass cap should be resurveyed.

Video Logs: yes ☐ no ☒ date _____

Signature and date: _____ Boe Reynolds 11/11/03

Well jettied /cleaned:	yes	no	X	date

Performed by: Dynatec

Figure 2-19. Well modification log for PW-4.

2.20 ICPP-MON-P-002 (MW-2)

WELL ID: 1058

1. Project Name: INTEC Well Maintenance for FY 2003
 2. Well Location: INTEC
 3. Date Maintenance Performed: Started: 5/5/03 Completed: 5/5/03
 4. Video Log Information: Video logging was not performed on this well.
 5. Maintenance Performed: Maintenance at MW-2 consisted of welding the base of the wellhead box to the surface casing.
 6. Observations Recorded: Surface completion pads and impingement posts were in excellent condition.
 7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT
- Field Lead: B. Reynolds/W. Jolley
- Crew: S. Tawater, M. Becker, and I. Perkes

WELL ID 1058

WELL NAME ICPP-MON-P-002 (MW-2)

PROJECT NAME FY 03 Well Maintenance at INTEC

Reason for modification: Secure the wellhead box.

Well Modification Log

START DATE 5/5/03

INSTALLATION TEAM Dynatec

END DATE 5/5/03

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ yes ☒ no

Are measurements from top of casing or land surface? NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
--------------------------------	--

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Comments: A tack weld was placed where the well head meets casing to secure the well head box.

Video Logs: yes no X date

Well jetted /cleaned: yes no X date

Performed by: Dynatec

Signature and date: Boe Reynolds 8/5/03

Figure 2-20. Well modification log for ICPP-MON-P-002.

2.21 ICPP-MON-P-018 (MW-17)

WELL ID: 1073

1. Project Name: INTEC Well Maintenance for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/8/03 Completed: 5/12/03
4. Video Log Information: Video logging was not performed on this well.
5. Maintenance Performed: Maintenance at MW-17 consisted of installing a single-phase, 30A, 125/250V (NEMA # L14-30) electrical plug so perched water can be sampled. A pump test was performed on 5/12/03. MW-17 is completed in a perched zone at approximately 381 ft bls. Once the pump was turned on, operational readiness was good; however, no water existed at this zone (360 to 381 ft bls). The pump is set at approximately 375 ft bls in the 4-in. casing at MW-17.
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/W. Jolley

Crew: S. Tawater, M. Becker, and I. Perkes

Well Modification Log

WELL NAME ICPP-MON-P-018 (MW-17) START DATE 5/8/03 END DATE 5/12/03

WELL NAME: _____
PROJECT NAME: _____
FY 03 Sitewide Well Maintenance
INSTALLATION TEAM: _____
START DATE: _____

Reason for modification: Install a 30-amp, 125/240-volt electrical plug.


Elevation of brass can? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ NA ☒ yes ☐ no

Are measurements from top of casing or land surface? NA



<i>Pump Modification</i>	Type	
	Manufacturer	
	Model #	
	Pump length	
	Top of pump	
	Bottom of pump	
	Inlet depth	
	Horse power	
	Flow rate	
	Head	None (dry)
	Volts, Amps, Kw	
	Phase	
	Material	
	Motor leads/Plugs	30 amp, 125/250 volt

<i>Protective Casing</i>	
Material	Not Modified
Diameter	
Height above ground (stick-in)	

Well Description	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	NA	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification	
Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification	
Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point	
Height above ground (stick-up)	Not Modified

Well Casing	
Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

The pump was tested, but it was determined that the well was dry on 5/12/03.

/ideo Logs: yes ☒ no ☐ date _____
 Signature and date: _____
 Boe Revnolds 8/5/03

Well jetted /cleaned: yes _____ no ☒ date _____

Performed by: Dynatec

Figure 2-21. Well modification log for ICPP-MON-P-018.

2.22 ICPP-MON-P-019 (MW-18)

WELL ID: 1187

1. Project Name: INTEC Well Maintenance for FY 2003
2. Well Location: INTEC
3. Date Maintenance Performed: Started: 5/6/03 Completed: 5/12/03
4. Video Log Information: Video logging was not performed on this well.
5. Maintenance Performed: Maintenance at MW-18 consisted of replacing the existing pump and electrical cable located in the 4-in. well casing. On 5/6/03, 460 ft of 3/4-in. water-level access line, the discharge line (475 ft), and the pump were pulled. The new pump, wired to new 8-gauge electrical cable, was attached to the original stainless-steel discharge line and lowered to a depth of 475 ft bls. On 5/12/03, the pump was tested to ensure operational readiness.
6. Observations Recorded: The surface completion concrete was in very good condition. The pump also appeared to be in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/W. Jolley

Crew: S. Tawater, M. Becker, and I. Perkes

Well Modification Log


Well Modification Log					
WELL ID 1187	ICPP-MON-P-019 (MW-18)	START DATE 5/06/03	END DATE 5/12/03		
WELL NAME PROJECT NAME FY 03 Well Maintenance at INTEC	INSTALLATION TEAM Dynatec				
Reason for modification: Replace pump		Elevation of brass cap? Not Changed Stick up of well casing? Not Changed			
Is this a pump replacement? <input checked="" type="checkbox"/> yes <input type="checkbox"/> no		If yes was pump returned to original depth? <input checked="" type="checkbox"/> yes <input type="checkbox"/> no		Satisfactory Needs repair	
Are measurements from top of casing or land surface? Land Surface					
Use diagram explain modification					
					
Pump Modification					
Type	Submersible				
Manufacturer	Grundfos				
Model #	10S20-27				
Pump length	41 in.				
Top of pump	475 ft.				
Bottom of pump	478.5 ft				
Inlet depth	Not recoreded				
Horse power	2 horse				
Flow rate	0.3 gpm				
Head	Not measured				
Voltis, Amps, Kw	230V/6.7A/1.5 KW				
Phase	3 phase				
Material	Stainless Steel				
Motor leads/Plugs	8 gauge (30A/600V plug)				
Protective Casing					
Material					
Diameter					
Height above ground (stick-up)					
Measure Point					
Height above ground (stick-up)					
Well Casing					
Material					
Diameter					
Height above ground (stick-up)					
Depth BLS					
Comments:					
Installed pump. No other modifications were made.					
Video Logs: yes no X date Signature and date: Boe Reynolds 9/05/03					
Well jetted /cleaned: yes no X date Performed by: Dynatec					

Figure 2-22. Well modification log for ICPP-MON-P-019.